

University of California, Riverside  
 Seismic Safety Program (Poor and Very Poor)  
 Completed Since 1990, Underway, Remaining to be Done

S = State-supported  
 NS = Non-State-supported  
 MC = Medical Center

a = Building sold or demolished; remove from priority list  
 b = Building rating upgraded to Fair or Good as a result of engineering study; rem  
 c = Seismic rehabilitation work completed; remove from priority list  
 d = Seismic rehabilitation work in progress (i.e., design or construction)  
 e = Project proposed for the year indicated

shading indicates project is active in capital program

S/ NS/ MC	BUILDING NAME	STATUS AS OF 3/31/2005	COMMENTS
S	BELL TOWER	c	Completed 1991
S	PHYSICS COLONNADE	c	Completed 1991
S	PHYSICS (North Wing)	c	Completed 1993
NS	BANNOCKBURN-MASONRY UNITS	c	Completed 1993
S	SOILS & NUTRITION 1 & 2	c	Completed 1993
S	GEOLOGY	c	Completed 1998
S	PHYSICS (South Wing & Center)	c	Completed 1998
S	VECTORIUM	a	Demolished 1999
S	PIERCE HALL	c	Completed 2000
S	BOYCE HALL (Webber Hall East)	c	Completed 2001
S	RIVERA LIBRARY (Addition & Library South)	c	Completed 2001
S	BATCHELOR HALL	c	Completed 2003
S	HUMANITIES/OLMSTED HALL	c	Completed 2004
S	ENTOMOLOGY ANNEX	a	Demolished 2004
S	HINDERAKER HALL	c	Completed 2004
S	FAWCETT LABORATORY	c	Completed 2004
S	LIFE SCIENCES UNIT 2 (1965 Add)	c	Completed 2004
S	SPROUL HALL	c	Completed 2004
S	INSECTARY BUILDING	d	State funds (to be demolished 2006-07)
S	ENTOMOLOGY (1932 Constr.)	d	State funds (to be demolished 2006-07)
S	Culver Center (Rouse Building)	e	State funds (2006-07)
NS	HIGHLANDER HALL, BLDG. A	e	95-96 Study to be re-assessed in 2005-06

rove from priority list